KA

Petrol Station Inspection Form



		A180 (Eas						
Name of Licensee(s)		North East		mmingham				
					A180 (East), Habrough, Immingham			
			North East Lincolnshire. DN40 3BH					
	***************************************				01-1	101		
	Name of Licensee(s)		Gradebrook Fillig Station Lld					
Jagintarad (Attion		1015 0	<u> </u>	24	2 1-			
Registered Office		24B Crown Street Breatwend EDROX CMILLY BA						
Authorisation/Permit Reference			EP/200200021/V2					
	0.0.0.0.00		J J J J J J J J J J J J J J J J J J J			1 60		
nspection date and du	ıration	2/2	1	01	Coll	als N		
•		3/2	2014	21	D' FP/	. ^ 2 -		
Inspector's name		Canil	GRAHAM BARR					
		CKAKH	4~ DA	4<				
Person met on site		\mathcal{M}						
(Name & Position)		11/0 Named.						
Six yearly review	of permi	January 20	012					
conditions undertaken								
Weather/Site Conditions		Dry	Recently	Rained F	Raining	Windy		
2. Inspection	Routine	Follow up	Complaint	New	Revised	4 year		
Related to:	visit	visit	investigation	application	application	review		
Fick relevant box:	VIOIC	V1016	mvootigation	application	apphoadon	1001000		
Total Control of the	/					sassayous and a sassayous a sassay		
***************************************			I			L		
2. Recent History of t	he Authorisa	ition Proces	s/Installation (since last ins	pection)	••••		
Number of justified con	nplaints (ever	ı if zero)	None		***************************************			

2. Recent History of the Authorisation Process	/Installation (since last inspection)
Number of justified complaints (even if zero) within the last 12 month period	None
Process/Installation changes since last inspection relevant to the Permit/Authorisation (Variation required) (Condition 6)	Wone
Process/Installation changes since last inspection NOT relevant to the Permit/Authorisation (Variation not required) (Condition 6)	None

3. Documentation on site	Comments
Is there a copy of the permit on site?	7301
Date of last inspection	11/2/2014
Are Petroleum Delivery Certificates kept?	Yes
Is the incident logbook present (Condition 24) Any incidents of vapour leaks? (Condition 3) Any incidents of vapour locks? (Condition 5)	230
Is the certification for the servicing of the vapour recovery system (Condition 22) and pressure relief	Los

valves present on site (every 3 years) (Condition 23)?	Yes
Are the following recorded in the logbook (Cond. 24)	
Maintenance inspections	1
Examinations and testing	
Inventory checking	
Installation and repair work carried	
Are there training details for staff and competence	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
records (Cond. 24 and 26)	200
4. External Inspection	Comments
Total number of tanks	
Number of tanks holding unleaded/leaded	L
replacement:	
Are they vented through the manifold?	Yes
Number of tanks holding diesel:	3
Are they vented separately?	Yes
Are connection points on tank filling pipes and vapour	
return pipe fitted with secure seals? (Cond. 9)	7.40
Are the fittings for delivery and vapour return pipes	
different? (Cond. 10)	7, minutes
Are connections for vapour return and delivery hose	
clearly locked and labelled? (Cond.13)	100
Is there clear notices/signage near the vapour return	
connection point reading:	200
-"connect vapour return line before off loading";	
-"the maximum number of tanker compartments which	
can be discharged"	(No more than two can be discharged –
	excluding the diesel compartments)
Are pressure relief valves fitted on petrol storage tank	
vent pipes? (Cond. 11)	
Are deliveries driver controlled?	
If yes, are the following functioning correctly:	No
1. Lights	
2. Phone alarm	
3. Tank capacity printout	
4. emergency procedures	

5. Checklist During Deliveries	Comments
Is a competent person overseeing the delivery? (Condition 16)	Les
Is manual dip testing carried out before delivery, and are dip openings securely sealed before delivery? (Condition 14)	Floctore
Is the vapour return hose connected before the delivery hose, with the tanker end connected before the storage tank (Condition 12)	Les
Are more than 2 tanker compartments discharged at once? (Condition 8)	No

Is the delivery hose disconnected before the vapour return hose, at the road tanker end first? With the vapour recovery hose disconnected at the storage tank end first (Condition 18)	Los
Are all road tanker vents and discharge valves closed on completion of delivery? (Condition 17)	Yes
Are all connection points securely sealed after delivery? (Condition 19)	Zen

6. Further Information	
Number of deliveries Annually	
Deliveries day or night	-
Last Maintenance Check 3 2 2014.	
Valous Cartal System Lld	
	7
6.1 Recommendations and Actions Required Cartification VFP 1402	- Communication
·	
+ One AdBlue above ground lak	
The following and the following the followin	
see See 14	

	-

