EJU 40484 Nov L172

Petrol Station Inspection Form



1. General Informatio	n							
Local Authority		North Fast	North East Lincolnshire Council					
Name/address of site			Cleethorpe Filling Station, 178 – 182 Cleethorpes Road,					
Name/address of site			Grimsby, N.E.Lincs DN31 3HW					
Name of Licensee(s)		Muse	Mussa Paterlas Ital					
Registered Office		4 56	Le St. Albon Hortadohie					
3.00		Boson	Bosonshield Ave ALIBRH					
Authorisation/Permit Reference			EP/200300100/V1					
land the said down the said		1 1						
Inspection date and duration		27/i/-	27/1/2013 2/0.					
Inspector's name								
mapedial a fiame		Grah	Graham Dans					
Person met on site		70010/0	70010/001					
(Name & Position)			JANDYAH YOYARASA (CONTRACT MANAYER)					
Six yearly review of permit		t				I.		
conditions undertaken								
Weather/Site Conditions	S	Dry	Recently I	Rained F	Raining	Windy		
					T =			
2. Inspection	Routine	Follow up	Complaint	New	Revised	4 year		
Related to:	visit	visit	investigation	application	application	review		
Tick relevant box:								
	V			<u></u>				
2. Recent History of th	e Authorisa	ation Proces	s/Installation (since last ins	spection)			
Number of justified complaints (even			T .					
within the last 12 month period			0					
Process/Installation changes since la								
inspection relevant to the Permit/Auth		thorisation	0					
(Variation required) (Co								
Process/Installation cha	ast							
inspection NOT relevan	· · · · · · · · · · · · · · · · · · ·							
Permit/Authorisation (Va	equirea)							
(Condition 6)								
3. Documentation on site Comments								
Is there a copy of the pe	ermit on site	?	You	2	11-1			
Date of last inspection Are Petroleum Delivery	leant?	17/4/	2013 nex	it look 17	14/2014			
Are retroleum Delivery	Certificates	KEDI (1 1			1 1		

Is the incident logbook present (Condition 24)

Is the certification for the servicing of the vapour recovery system (Condition 22) and pressure relief valves present on site (every 3 years) (Condition 23)?

Any incidents of vapour leaks? (Condition 3) Any incidents of vapour locks? (Condition 5)

Are the following recorded in the logbook (Cond. 24)	* · · »
Maintenance inspections	
Examinations and testing	Les
Inventory checking	
Installation and repair work carried	
Are there training details for staff and competence	. 2
records (Cond. 24 and 26)	Yes
4. External Inspection	Comments
Total number of tanks	4
Number of tanks holding unleaded/leaded	2
replacement:	
Are they vented through the manifold?	کمک
Number of tanks holding diesel:	2
Are they vented separately?	Yes
Are connection points on tank filling pipes and vapour	
return pipe fitted with secure seals? (Cond. 9)	720
Are the fittings for delivery and vapour return pipes	1
different? (Cond. 10)	Les
Are connections for vapour return and delivery hose	
clearly locked and labelled? (Cond.13)	
	Les habels seguire
Is there clear notices/signage near the vapour return	flooring complete
connection point reading:	at time dat
-"connect vapour return line before off loading";	inglaction
-"the maximum number of tanker compartments which	(Alamana than tanana tha dia dan and
can be discharged"	(No more than two can be discharged –
And processing well-of such as of the dear and at any any and at any any and at any any any and at any any and at an	excluding the diesel compartments)
Are pressure relief valves fitted on petrol storage tank vent pipes? (Cond. 11)	Les
Are deliveries driver controlled?	n (
If yes, are the following functioning correctly:	\mathbb{N}_{\circ}
1. Lights	
2. Phone alarm	
3. Tank capacity printout	
4. emergency procedures	

5. Checklist During Deliveries	Comments
Is a competent person overseeing the delivery? (Condition 16)	Ves
Is manual dip testing carried out before delivery, and are dip openings securely sealed before delivery? (Condition 14)	Verder Root Print
Is the vapour return hose connected before the delivery hose, with the tanker end connected before the storage tank (Condition 12)	Les
Are more than 2 tanker compartments discharged at once? (Condition 8)	No

Is the delivery hose disconnected before the vapour return hose, at the road tanker end first? With the vapour recovery hose disconnected at the storage tank end first (Condition 18)	200
Are all road tanker vents and discharge valves closed on completion of delivery? (Condition 17)	Los
Are all connection points securely sealed after delivery? (Condition 19)	Yes

6. Further Information
Number of deliveries Annually
Deliveries day or night
Last Maintenance Check
Next test due 17/4/2014.
6.1 Recommendations and Actions Required

2275\$27222 Anlm:

₩ 8