## **POLLUTION PREVENTION & CONTROL**



## PERMIT CONDITIONS COMPLIANCE CHECK REPORT

Installation Address:	North East Lincolnshire Council Crematorium Weelsby Avenue Grimsby North East Lincolnshire DN32 7AU
Contact:	
Permit Ref:	200200091/V2
Date of Varied Permit:	25.03.10
Permitted activity:	Crematorium
Guidance Note:	PG5/2 (04)
Date of Visit:	18.12.18 10/07/14
Report Reference:	NEC1 check visit only
Condition number:	The state of the s
<b>5.1</b> Reference Cond 273K,	Checked display
101.3kPa?.	Screen - record su
See Table 2	checked display screen-records
HCL annual extractive (200mg/m3	Oxygen cantinuous
TPM Cont + Annual extract	
CO Cont + Annual extract	monitoring I display. always reads Onglin??
Organic comp annual	reads Onolar?
Temperature & Oxygen continuous	
5.2 Monitoring records	Received 6 monthly reports
Alarm activations recorded?	will check further
(Temperature and Oxygen)	reports during full compliance
5.3 Notify NELC 7 days before	Due later.
testing and forward results?	
5.4 Visual and odour check	No nilpro or odoni
recorded at least once a day during	g emissions during visit
operation? Any Vis emissions/odo	ur? Vist odas checks recorded.
<b>5.5</b> Abnormal events recorded?	Yes.
5.6	
5.7 Cont monitor – calibrated/	To chack on Full compliance

## **POLLUTION PREVENTION & CONTROL**

activation alarm recorded?	V/ -
Continuous readings on display to	Yes.
trained staff?	
Activation of alarms automatically	
recorded?	
5.8	
5.9 Monthly/4 weekly reports	Yes.
available?	
5.10	
5.11	
5.12	
5.13	
5.14	Informative
5.15	Informative
5.16 Annual extraction meets BS	
ISO 9096?	
5.17 N/A	Mercury abatement installed
5.18 N/A	
5.19 Informative	
6.32 Training	- Check during Full
6.33 Maintenance	
Programme?	le n i e
Maintenance checks	
recorded?	10 10 10
Cleaning schedule?	10 11
<b>7.2</b> Sent by the 1 <sup>st</sup> April 2011 the	
certificate from Cameo organisation	Yes ·
number of cremations in past 12	
months?	