

PERMIT CONDITIONS COMPLIANCE CHECK REPORT

Installation Address:	Cemex UK Operations Ltd. Gilbey Road Pyewipe Grimsby DN31 2SJ	
Contact:	Colin Burdett	
Permit Ref:	200200083/V2	
Date of Varied Permit:	March 2014	-
Permitted activity:	Coated Roadstone / Reduced fee activity	-
Guidance Note:	PG3/15(04)	-
Date of Visit:	06/05/15	1
Report Reference:		
Condition number:	(A)	-
No visible emissions beyond site	No visible emissions	-
boundary?	duting visit.	
Emission monitoring completed	last emission (perhautate) test 7th Aprilo	
(Table 1)	Result 26 mg/m3 Viscol charles	1 500 501
Maintenance plan on abatement	conveyor + water pumps weally checks.	CABITELLIONEDI.
equipment and dust control plant	Daily high level charm checks.	
Recycled asphalt pavement	checks on hotbins.	
containing coal tar identified and		
stored separately from other	All bitumen no tor.	
asphalt and processed only		
using cold methods		
Silos Fillers and bitumen only	Yes.	
stored within filler and bitumen silos?		
Silos Dust emissions from	Con	
loading or unloading tankers	⊘	
minimised by back venting to a		
delivery tanker fitted with	*	
onboard trunk mounted relief		

valve and filtration system	
Silos fitted with overfilling alarm?	Yes
Silos deliveries must stop	
automatically where over-	
pressurisation or over-filling	
identified. (new silos after 2004)	
Silos displaced air from	
pneumatic transfer shall pass	*
through abatement prior to	
emission to air	20,
Aggregates delivery and	Yes.
Storage material stored in	
designated areas?	
Belt conveyor fully enclosed	Yes - conveyor Fully
and transfer points have wind	Yes - conveyor tully enclosed.
protection / chute for free fall of	OC/GREEK T
material	
Loading and unloading	Yes + written procedure.
Vehicles carrying dusty product	
sheeting when arriving / leaving	
site?	_ _ _ _ _ _
Roadways have consolidated	
surfaces and kept clean / good	0.12
repair?	
Vehicles not tracking material	Her at a
onto highway?	Compliant and procedure available
Process buildings maintained	Yes - in daily check list.
and checked for build-up of	
material to minimise emissions?	
Records	Yes
Staff training	Yes. Environmental Awareness

Risk Assessment Score Sheet

Operator Performance Appraisal

Component 5 - Compliance Assessment		
Scale of Non-Compliance (Within 12 month period prior to review)	Possible Scores	Score Awarded
(A) Incident leading to justified complaint but no breach of specific authorisation condition or of general/residual BATNEEC condition	0 points	0
(B) Incident leading to a justified complaint*	5 per incident	0
(C) Breach of authorisation not leading to formal action (Updated by AQ 18)	10 per breach	0
(D) Incident leading to formal caution, Enforcement Notice or prosecution	15 per incident	0
(E) Incident leading to a Prohibition Notice	20 per incident	0
Total	(Max. 50)	0

^{*} Unjustified complaints may be e.g. those considered by the inspector to be unreasonable or which cannot be clearly linked to an incident at the process.

3		ossib Score	Score Awarded	
Criterion	(x) Yes	(y) No	(z) N/A	
(A) All monitoring undertaken to the degree required in the authorisation?	0	10	0	Уб
(B) Monitoring requirements reduced because results over time show consistent compliance?	-5	0	0	NIAO
(C) Process operation modified where any problems indicated by monitoring?	0	5	0	NIA O
(D) Fully documented and adhered to maintenance programme, in line with authorisation?	0	5	0	γо
(E) Full documented records as required in authorisation available on-site?	0	5	0	γo
(F) All relevant documents forwarded to the authority by date required?	0	5	0	уО
Total score	(-5 to 30)		0	

Component 7 - Assessment of Management,	Trainir	ng and	l Resp	onsibility
	Possible Scores		Scores Awarded	
Criterion	(x) Yes	(y) No	(z) N/A	
(A) Documented procedures in place for implementing all aspects of the authorisation?	0	5	0	уо
(B) Specific responsibilities assigned to individual staff for these procedures?	0	5	0	Y 0
(C) Completion of individual responsibilities checked and recorded by the company?	0	5	0	YO
(D) Documented training records for all staff with air pollution control responsibilities?	0	5	0	уо
(E) Trained staff on site throughout periods where potentially air-polluting activities take place?	0	5	0	УО
(F) Is an 'appropriate' environmental management system in place?	-5	0	0	y - 5
Total	(-	5 to 2	5)	-5

Total Score for Operator Performance Appraisal	Range -10 to 105	-5
--	------------------	----

OVERALL SCORE FOR THE PROCESS	Range -10 to 175	-5
REGULATORY EFFORT CATEGORY * high=score of >60, medium 30-60 and low <30*	LOW, MED, HIGH	Low

Officer: VICKY THOMPSON

Officer Signature: V. Thom

Operator Signature

Date: 06105/15