


PERMIT CONDITIONS COMPLIANCE CHECK REPORT

Installation Address:	Paragon Automotive Ltd. Estate Road No. 5 South Humberside Industrial Estate Grimsby North East Lincolnshire DN31 2TG
Contact:	Ian Cowdroy
Permit Ref:	EP/200200081/V1
Date of Varied Permit:	
Permitted activity:	Coating Process
Guidance Note:	PG 6/34b(06)
Date of Visit:	21/06/13
Report Reference:	SITE NOT IN USE.
Condition number:	
1.1 Any persistent visible emissions?	
1.2 All emissions to air free from droplets?	
1.3 Compliant paints, primers etc used?	
1.4 Emissions from combustion meet Ringlemann shade 1?	
1.5 No offensive odour beyond site boundary?	
1.6 No odour masking agents used?	
1.7 Any changes to spray booths? Last service of spraybooths?	
1.8 Spraybooths meet emission limit?	
1.9 HVLP spray guns used to apply primers and top coats?	
1.10 Any changes to centralised extraction system? Last Serviced?	
1.11 Notification	

LOW RISK - SITE CURRENTLY NOT IN USE - To notify when site

Report Reference: - re-open.

(Regulator) V. Wang 21.06.13. (Operator)

